GLACIER NATIONAL PARK JOB SAFETY ANALYSIS (JSA)

Job Title:	Date:	x NEW
CHAINSAW OPERATION		REVISED
Job Location:	Division:	Branch:
Name of Employee(s) Involved in Analysis:	Supervisor:	Division Chief:

KEY STEPS	HAZARDS	SAFETY PROCEDURES	RESPONSIBILITY
KEY STEPS Chainsaw Use ad Operation	HAZARDS General	SAFETY PROCEDURES ALL OPERATORS OF CHAINSAWS ARE REQUIRED TO HOLD A QUALIFICATION CARD WITH A MINIMUM PROFICIENCY LEVEL OF INTERMEDIATE "B" SAWYER. REFRESHER CLASSES WILL BE ATTENDED EVERY YEAR AND REFRESHER AND FIELD EVALUATION WILL BE ACCOMPLISHED EVERY THREE YEARS. APPROPRIATE PPE WILL BE WORN AT ALL TIMES WHEN OPERATING CHAINSAWS. THIS INCLUDES: EYE PROTECTION, EAR PROTECTION, HARD HAT, LEATHER GLOVES LONG SLEEVED SHIRT, SAW CHAPS, AND HEAVY DUTY ALL LEATHER BOOTS WITH 8" TOP AND NON-SKID SOLES. ALSO, FIRST AID KIT AND FIRE EXTINGUISHER WILL BE KEPT IMMEDIATELY AT HAND DURING SAWING OPERATIONS. MAINTAIN SAW IN GOOD OPERATING CONDITION. WHEN SHARPENING CHAIN, WEAR GLOVES, SAFETY GLASSES, AND FILE GUARDS.	RESPONSIBILITY
		ALL SAWS MUST BE EQUIPED WITH A CHAINBRAKE. USE AN APPROVED CLEARLY MARKED CONTAINER FOR GAS AND OIL. REFER TO APPROPRIATE HAZARDOUS MATERIAL JHA. ALLOW SAW TO COOL AT LEAST 5 MINUTES BEFORE REFUELING. IMMEDIATELY CLEAN UP SPILLED FUEL. REFUEL OUTDOORS AND AT LEAST 20 FEET FROM OPEN FLAME OR OTHER SOURCES OF IGNITION. PAY ATTENTION AT ALL TIMES!!! NEVER, NEVER OPERATE SAW WHILE WORKING ALONE!!!	

KEY STEPS	HAZARDS	SAFETY PROCEDURES	RESPONSIBILITY
		KNOW WHERE YOUR FELLOW WORKERS ARE AT ALL TIMES!!!	
		KEEP FELLOW WORKERS AT A SAFE DISTANCE FROM SAWING OPERATIONS.	
		MAINTAIN A SECURE GRIP ON THE SAW AT ALL TIMES.	
		ALWAYS START SAW WITH THE CHAIN BRAKE ENGAGED. START SAW ON THE GROUND OR WHERE OTHERWISE FIRMLY SUPPORTED. "DROP STARTING" SAW IS NOT PERMITTED!	
		WHEN CARRYING SAW FOR SHORT DISTANCES, ACTIVATE CHAIN BRAKE. FOR LONGER DISTANCES, SHUT SAW OFF AND INSTALL BAR AND CHAIN GUARD.	
		BE SURE OF YOUR FOOTING. KEEP WORK AREA CLEAN AND AVOID TRIPPING HAZARDS.	
		MAINTAIN A COMFORTABLE POSITION! CUTTING WITH THE POWER HEAD POSITIONED BETWEEN THE WAIST AND SHOULDER SHOULD BE CONSIDERED AS A DANGER ZONE. CUTTING WITH THE POWERHEAD POSITIONED ABOVE SHOULDER HEIGHT IS NOT PERMITTED.	
		DO NOT POSITION YOURSELF IN SUCH A WAY THAT YOU CANNOT MOVE ABOUT FREELY. LEAVE YOURSELF AN ESCAPE ROUTE.	
		KNOW WHERE THE TIP OF THE BAR IS AT ALL TIMES. "PLUNGE" CUTTING CAN CAUSE SERIOUS "KICKBACK" AND SHOULD ONLY BE ATTEMPTED BY WORKERS WITH DEMONSTRATED COMPETENCY.	
		BE SURE LOGS ARE BLOCKED OR SECURED BEFORE BEGINNING SAWING OPERATIONS. KNOW WHERE "LOG DOGS" ARE LOCATED.	
		WHEN BUCKING, ALWAYS WORK FROM THE UPHILL SIDE.	
		IF USING SAW INDOORS, ENSURE THERE IS ADEQUATE VENTILATION!	

KEY STEPS	HAZARDS	SAFETY PROCEDURES	RESPONSIBILITY
PREPARATION: GETTING	WRONG FUEL AND/OR	CHECK CAHIN AND BOLT TIGHTNESS, CHECK CHAIN BRAKE,	SUPERVISOR/
FUEL, TOOLS, SAFETY	OIL, FUEL SPILLAGE,	READ OPERATOR'S MANUAL FOR CORRECT FUEL AND SAFE	EMPLOYEE
EQUIPMENT	INSUFFICIENT SAFETY	OPERATING PROCEDURES. MAKE SURE PERSONAL SAFETY	
	EQUIPMENT, SLIPS,	EQUIUPMENT FITS AND IS IN GOOD WORKING ORDER	
	LOOSE CHAIN/BOLTS		
CLEAR WORK AREA	TRIPPING, OTHER	CLEAR JOB SITE OF TRIPPING HAZARDS AND CLEAR OF OTHER	EMPLOYEE
	EMPLOYEES BEING	EMPLOYEES	
	STRUCK BY FALLING		
	OBJECTS		
STARTING AND WARMING	FLOODING ENGINE,	SET CHAIN BREAK, CLEAR CHAIN PASSAGE, SECURE SAW WHILE	EMPLOYEE
UP OF CHAIN SAW	LOSS OF CONTROL,	STARTING, IDLE TO OPERATING TEMPERATURE	
	CUT FROM CHAIN,		
	SAW KICKBACK, FIRE		
OPERATION	KICKBACK, CUTS	READ OPERATING INSTRUCTIONS AND KNOW HOW TO USE SAW	EMPLOYEE
	FROM CHAIN,	SAFELY, KNOW FELLING TECHNIQUES, HOW TO AVOID	
	WHIPBACK, BEING	KICKBACK AND PINCHING. TURN OFF SAW WHEN MOVING.	
	STRUCK FROM	HAVE SECURE FOOTING. DO NOT USE SAW THAT IS TOO	
	FALLING TREES,	BIG	
	WRENCHING FROM		
	PINCHED BAR, FIRE,		
	BACK INJURIES		
REFUELING	FIRE, EXPLOSION,	COOL DOWN SAW BEFROE REFUELING. POUR FUEL CAREFULLY	EMPLOYEE
	TRIPS, SLIPS	AND SLOWLY, AVOID SPILLS. AVOID	
		OPEN FLAMES AND SMOKING	
SHUTDOWN	SLIPPERY SURFACES,	DO NOT WALK ON LOGS, SLIPPERY, OR OILY SURFACES. PUT	EMPLOYEE
	BOUND BRANCHES,	GUARD ON CHAIN. DO NOT TOUCH HOT SAW. RELIEVE PRESSURE	
	HEATED SURFACES,	ON BOUND MATERIAL	
	BACK INJURIES,		
	SHARP CUTTING		
	EDGES		
CLEANUP AND STORING	CUTS FROM SHARP	CLEAN UP WORK AREA. CLEAN AND SHARPEN SAW AND ENCASE	EMPLOYEE
	EDGES, FIRE, BACK	CHAIN IN GUARD. DEFUEL BEFORE STORING. STORE RELATED	
	INJURIES, TRIPPING	TOOLS PROPERLY	